


REVISIONS			
REV.	DESCRIPTION	DATE	APPROVED
Α	INITIAL RELEASE	02/21/2022	AGANWANI








STRIPPING DIMENSIONS

ASSEMBLY PROCEDURE

- 1. STRIP CABLE AS SHOWN. DO NOT NICK CENTER CONDUCTOR.
- 2. PLACE CONTACT OVER CENTER CONDUCTOR. SOLDER CONTACT TO CENTER CONDUCTOR.
- 3. INSERT CABLE AND CONTACT INTO CONNECTOR BODY UNTIL FULLY ENGAGED. SOLDER CABLE TO BODY.



MOUNTING HOLE DETAIL (MOUNTING HARDWARE TO BE DETERMINED BY USER)

THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

