

ASSEMBLY INSTRUCTIONS:

- ω_.ν_.-STRIP THE CABLE AS SHOWN. DO NOT NICK CENTER CONDUCTOR.
- SLIDE THE FERRULE (D) OVER THE CABLE JACKET.
 PLACE THE GASKET (C) AND THEN THE CONTACT (B) ONTO THE
- CONDUCTOR. CENTER CONDUCTOR. SOLDER CONTACT TO CENTER
- 4. THE REAR END OF THE CONNECTOR (A). LOOSEN THE CABLE BRAID, THEN SLIDE THE CONNECTOR (A) INTO PLACE. THE CABLE BRAID MUST OVERLAP THE KNURLED SECTION AT
- SLIDE THE FERRULE (D) OVER THE CABLE BRAID AND CRIMP IN

5

THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.



an INFINIT® brand

TIT IE

