









## STRIPPING DIMENSIONS

## NOTES:

2

- CABLE ATTACHMENT:

  OUTER: CRIMP.

  INNER: SOLDER.

  CRIMP SIZE REQUIRED:

  FERRULE: .128 [3.25] HEX. CRIMP TOOL.

  CONTACT: SOLDER.

## STANDARD TOLERANCES .X ±0.2 .XX ±0.01 .XXX ±0.005

\*STANDARD TOLERANCES APPLY ONLY TO DIMENSIONS IN INCHES

H	н
2	בֿי
Ε	-
	7
1	7.
	Ď
~	2
-	_
	Ş
7	2.
ì	3
	2
~	3
2	ע
<	4
	D

an INFINIT® brand

TITLE

CAD FILE	DWG NO	NOTES: 1. UNLESS 2. ALL SPEC 3. DIMENSI
06/24/19 SHEET	FMCN1577	NOTES: 1. UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE NOMINAL. 2. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME 3. DIMENSIONS ARE IN INCHES [mm].
SHEET		
1 OF 1		ALL DIMENSIO ECT TO CHANGE nm].
SCALE		NS ARE I
N/A	CAGE CODE	JT NOTIC
SIZE A		E AT ANY T
7361	3FKR5	IME.