


NOTES:

- CABLE ATTACHMENT:

Ņ

- OUTER: CRIMP.
 INNER: SOLDER.
 CRIMP SIZE REQUIRED:
 FERRULE: .130 [3.30] HEX. CRIMP TOOL.
 CONTACT: SOLDER.



THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.





TITLE

≻	SIZE		X = ±.2 [5.08] XX = ±.02 [.51] XXX = ±.005[.13]		× +		
<u>ع</u>	CAGE CODE	ALL DIMENSIONS SHOWN ARE FOR REFERENCE ONLY.			TOLERANCES	SS OTHER	
3FKR5	Œ		FRACTIONS ± 1/32 ANGLES ± 1			NCES:	DIMENSIO
	무				CABLE LENGTH (L) TOLERANCES	NSIN	
K.DANG	DRAWN BY	N ARE FOR REFERE				UNLESS OTHERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES DIMENSIONS IN [] ARE MILLIMETERS	
SC9561	ITEM NO.	NCE ONLY.	L ≤ 12 [305] = 1 [25] / 0 12 [305] < L ≤ 60 [1524] = +2 [51] / -0 60 [1524] < L ≤ 120 [3048] = +4 [102] / -0 120 [3048] < L ≤ 300 [7620] = +6 [152] / -0 300 [7620] < L = +5%L / -0			(L) TOLERANCES:	S ARE INCHES
		SCALE N	SHEET 1	THE INFORMATION IN THE SIGN IN THIS IS THE PROFILE			
⊳	REV	N/A)F 1	ATION AND DOCUMENT ERTYOF EE CORPORATION. RESERVED. OF			