


- NOTES:
  1. CABLE ATTACHMENT:
   OUTER: CRIMP
   INNER: SOLDER/CRIMP
  2. CRIMP SIZE REQUIRED:
   FERRULE: .213 [5.41] HEX. CRIMP TOOL.
   CONTACT: .068 [1.73] HEX. CRIMP TOOL.



THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.



an INFINIT® brand

≻	SIZE	ALL DIMENSIONS SHOWN ARE FOR REFERENCE ONLY		× × × × × × × × × × × × × × × × × × ×	<     +		UNLE	
ဍ	CAGE CODE		X=±.2 [5.08] FRACTIONS XX=±.02 [.51] ±1/32 XXX=±.005[.13] ANGLES±1°		5 [5 08]	TOLERANCES:	UNLESS OTHERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES DIMENSIONS IN [] ARE MILLIMETERS	
3FKR5	DE				EBACTIONS			
DMAY	DRAWN BY		_			CABLE LENGTH (L) TOLERANCES		FIED LEADING DIMENSIO
FMCN1752	ITEM NO.	NCE ONLY.	120 [3048] < L ≤ 300 [7620] = +6 [152] / -0 300 [7620] < L = +5%L / -0	L ≤ 12 [305] = +1 [25] / -0	(L) TOLERANCES:	ONS ARE INCHES		
11752		SCALE N	THE INFORMATION AND DESIGN IN THIS DOCUMENT IS THE PROPERTY OF FAIRVIEW MICROWAVE CORPOGATION ALL RIGHT'S RESERVED.  SHEET 1 OF 1					THIRD-ANGLE PROJECTION
⊳	REV	N/A	¥ 1	CORPORATION. SERVED.	NOCUMENT		+\	OJECTION