

## NOTES:

- CABLE ATTACHMENT:

Ŋ

- OUTER: CRIMP.
  INNER: SOLDER.
  CRIMP SIZE REQUIRED:
  FERRULE: .213 [5.41] HEX. CRIMP TOOL.
  CONTACT: SOLDER.


THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

NGLE PROJECTION



an INFINIT® brand

III III III



N/A

REV